



<http://MYZEPHYRS.COM>

ESE-M2C144-A, SAE-10W-40 ENG. OIL OR ESE-M99B144-A LUBRICANT MAY BE USED AS AN AID FOR ASSEMBLY OF HOSES ON TUBES NO OTHER MATERIAL MAY BE USED.

\* INSTALL HOSE TO SECOND BEAD ON TUBE. CLAMP MUST BE ON HOSE AND FLUSH TO 1/8" FROM END OF HOSE WHERE APPLICABLE.

• INSTALL HOSE ONTO TUBES .62 MIN. CLAMP MUST BE ON HOSE AND FLUSH TO 1/8" FROM END OF HOSE WHERE APPLICABLE.

EXTENSION FRONT R.H. SIDEMEMBER **VIEW S**

# 14.0 GALLON Fairmont/Zephyr 2.3L/3.3L (200 CID)/4.2L (255 CID) Engines

ESE-M2C144-A, SAE-10W-40 ENGINE OIL MAY BE USED ON 9034 AND OR 9072 AS ASSEMBLY AID. NO OTHER MATERIAL MAY BE USED.

ESE-M2C144-A, SAE-10W-40 ENGINE OIL OR ESE-M99B144-A LUBRICANT MAY BE USED ON 9B593 AND OR 98076 AS AN ASSEMBLY AID. NO OTHER MATERIAL MAY BE USED.

CLIP MUST BE CENTERED ON 3/4" ORANGE OR RED TAPE ON VAPOR TUBE 9A228

LOCATE CLINCH EYELET ON VAPOR TUBE 9A228 IN FRONT OF AND ADJACENT TO CLIP 387772

CLIP MUST BE CENTERED ON 3/4" WHITE TAPE ON VAPOR TUBE 9A228 AT 3 PLACES MARKED

CLIP MUST BE CENTERED ON 3/4" BLUE TAPE ON VAPOR TUBE 9A228 ONE PLACE MARKED

VAPOR TUBE 9A228 MUST BE INSTALLED ABOVE TOOL CLEARANCE HOLE AS SHOWN

9A068 ATTACH TO TOP OF FUEL TANK WITH ESB-M2055-B OR ESB-M20149-A ADHESIVE.